



NUMBER: 08-044-05

GROUP: Electrical

DATE: August 16, 2005

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-028-01, DATED DECEMBER 28, 2001, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ADDITIONAL MODEL YEARS.**

SUBJECT:

Moisture In Headlamps

OVERVIEW:

This bulletin describes a normal headlamp condensation condition.

MODELS:

2002	(PG)	Chrysler PT Cruiser (International Markets)
2000 - **2005**	(PL)	Neon
2001 - **2006**	(PT)	Chrysler PT Cruiser

DISCUSSION:

Some moisture accumulation inside a vented headlamp assembly is normal. This normal moisture will appear as a fogging on the inside of the lamp lens (similar to the fog that sometimes appears on the inside of the windshield). This moisture may be removed by activating the headlamps on high beam for 15 minutes.

If water droplets larger than 1 mm in size have accumulated on the inside of the headlamp lens, the headlamp assembly should be replaced.

POLICY:

Information Only



Stick with the Specialists™