



NUMBER: 08-012-03

GROUP: Electrical

DATE: Apr. 25, 2003

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN IS BEING PROVIDED IN ADVANCE. DO NOT ORDER PARTS OR PERFORM ANY ACTIONS RELATED TO THIS BULLETIN UNTIL MAY 9, 2003.

SUBJECT:

Inadvertent Siren Activation

OVERVIEW:

This bulletin involves replacing and configuring an Alarm Remote Keyless Entry Module (ARKEM).

MODELS:

2002	(PG)	PT Cruiser (International Markets)
2000 - 2003	(PL)	NEON (International Markets)
2001 - 2003	(PT)	PT Cruiser (International Markets)

NOTE: THIS BULLETIN APPLIES TO VEHICLES EQUIPPED WITH A THATCHAM ALARM, SALES CODE LSC.

SYMPTOM/CONDITION:

Customer may describe inadvertent siren activation or security alarm activates for no apparent reason, can happen at any time.

DIAGNOSIS:

If this condition can be duplicated or customer describes this condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	04671880AC	Module, Alarm Remote Keyless Entry

EQUIPMENT REQUIRED:

CH6000A	Scan Tool (DRBIII®)
CH2002	General Purpose Interface Bus Cable Assembly

REPAIR PROCEDURE:

NOTE: AFTER INSTALLING A NEW ARKEM (RKE) MODULE IT MUST BE CONFIGURED USING THE DRBIII® SCAN TOOL AS DESCRIBED BELOW. THE DRBIII® SCAN TOOL MUST BE OPERATING AT LEVEL 56.0 OR HIGHER.

1. Replace the ARKEM (RKE) module as described in the appropriate service manual.
2. Hook up the DRBIII® Scan Tool to the Data Link Connector (DLC).
3. With the key in the ignition, turn the key to the RUN position.
4. After the DRBIII® Scan Tool initialization, perform the following:
 - a. Select "Theft Alarm".
 - b. Select "VTSS".
 - c. Select "Miscellaneous.
 - d. Select "Configure Module".
 - e. Select "Yes" for Current Configuration Display.
 - f. Press Any Key.
 - g. Select the number of the model year of the vehicle (**new requirement**).
 - h. Select the number of the body style of the vehicle.
 - i. Select the number for Left Hand Drive or Right Hand Drive.
 - j. Select the number of the Market.
 - k. Select the Desired VTA (module) Type.
 - l. The Current Configuration is displayed.
 - m. Reprogram the RKE (Key Fob) Transmitter(s).
5. The configuration is complete, disconnect the DRBIII® Scan Tool.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-80-28-92	ARKEM, Replace & Program	0.3 Hrs.

FAILURE CODE:

58	Internal Defect
----	-----------------