



**NUMBER:** 18-024-05

**GROUP:** Vehicle Performance

**DATE:** May 17, 2005

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.*

**THE DRBIII® FLASH FILES FOR THIS BULLETIN ARE AVAILABLE ON DealerCONNECT.**

**FOR MARKETS OUTSIDE OF THE UNITED STATES AND CANADA, THE FLASH FILES AND REPROGRAMMING INSTRUCTIONS WILL BE AVAILABLE ON ITIL/ISIS DVD JULY, 2005.**

**SUBJECT:**

Flash: Driveability Improvements

**OVERVIEW:**

This bulletin involves selectively erasing and reprogramming the Powertrain Control Module (PCM) with new software.

**MODELS:**

2003	(PL)	Neon
2003	(PT)	PT Cruiser
2003	(RS)	Town & Country/ Caravan/Voyager
2003	(RG)	Chrysler Voyager

**This bulletin applies to:**

- **PL vehicles equipped with a 2.0L engine (sales code ECB or ECH).**
- **PT vehicles equipped with a 2.0L or 2.4L engine (sales code ECC or EDZ).**
- **RS vehicles equipped with a 2.4L engine (sales code EDZ).**
- **RG vehicles equipped with a 2.4L engine (sales code EDZ).**



**Stick with the Specialists™**

**SYMPTOM/CONDITION:****All Vehicles**

The vehicle operator may experience idle fluctuation.

**PL Vehicles with a 2.0L Engine (sales codes ECH) or a 2.0L engine and manual transmission (sales code ECB and DD5 or DDR)**

The vehicle operator may experience one or more of the following:

- Hard start at temperatures between 9° C (48.2° F) and 65° C (149° F).
- RPM bump while driving when the A/C is turned on.
- RPM sag on throttle tip-in or tip-out.

**DIAGNOSIS:**

Using a Scan Tool (DRBIII®) with the appropriate diagnostic procedures on TechCONNECT, verify all engine systems are functioning as designed. If DTCs are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the Symptom/Condition is present, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	04275086AB	Label, Authorized Modification

**SPECIAL TOOLS/EQUIPMENT REQUIRED:**

NPN	Battery Charger
CH2002	General Purpose Interface Bus Cable Assembly
CH6000A	Scan Tool (DRBIII®)
CH7000A/7001A	J1962 Cable with red DRBIII® connector
	TechCONNECT Workstation

**NOTE: An updated J1962 cable has been released. This cable has a red colored connector at the DRBIII® connection. Use this cable whenever a flash is being performed.**

**REPAIR PROCEDURE:**

**NOTE: Whenever a controller is programmed, the software in the DRBIII®; must be programmed with the latest revision level available.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted and then follow the directions on the DRBIII®.**


1. Before beginning the reprogramming procedure, remove any old flash reprogramming files from the DRBIII® memory. To clear the memory from the MAIN MENU:

- a. Simultaneously press the "MORE" and "YES" keys.
- b. A screen will appear requesting a "COLD BOOT".
- c. Follow the on screen instructions by selecting the "F4" key.
- d. When the DRBIII® reboots to the MAIN MENU, proceed to [Step #2](#)
2. With the ignition switch in the "RUN" position, determine the original part number of the PCM currently in the vehicle. Using the DRBIII® select:
  - a. "DRBIII® Standalone"
  - b. "1998 - 2005 Diagnostics"
  - c. "All (Except Below)"
  - d. "Engine"
  - e. "Module Display"
  - f. Record the "PCM part #" on the repair order for later reference.
3. Connect the DRBIII® to TechCONNECT. Open TechTOOLS and verify that the "DRBIII® Status: Connected" message is in the upper right corner of the TechTOOLS screen.
4. Enter the "PCM part #" recorded in [Step #2](#) in the "Parts Criteria" area and select "Show Updates". TechTOOLS will populate the appropriate calibration.
5. Select the calibration.
6. Select the "DRBIII" radio button which is next to the "Download/Update" button.
7. Select the "Download/Update" button.
8. Monitor the "Flash Download/Update Progress" window on the TechCONNECT and follow the instructions on TechCONNECT. When the flash process is complete, proceed to [Step #9](#).
9. **Disconnect the DRBIII® from TechCONNECT.**
10. Open the hood, install a battery charger and verify that charging rate provides approximately 13.5 volts.
11. Connect the DRBIII® to the vehicle.
12. Download the flash from the DRBIII® to the vehicle. Using the DRBIII® select:
  - a. "Vehicle Flash"
  - b. Follow the directions on the DRBIII® screen. When the flash process is complete, proceed to [Step #13](#).

**NOTE: Due to the PCM programming procedure, a DTC may be set in other modules (TCM, BCM, MIC, SKIM, etc.) within the vehicle, if so equipped. Some DTC's may cause the MIL to illuminate. Check all modules using "Module Scan", record the DTC's, and erase these DTC's prior to returning the vehicle to the customer. Erase any DTC's in the PCM only after all other modules have had their DTC's erased.**

**NOTE: The following step is required by law.**

13. Type the necessary information on the "Authorized Modification Label" p/n 04275086AB and attach near the VECI label ([Fig. 1](#)).



**Fig. 1 AUTHORIZED MODIFICATION LABEL**

- 1 - POWERTRAIN CONTROL MODULE P/N (INSERT P/N) USED
- 2 - CHANGE AUTHORITY: TSB XX-XXX-XX
- 3 - DEALER CODE: XXXXX
- 4 - DATE: XX-XX-XX

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Amount
08-19-43-98	Reprogram Powertrain Control Module	0.8 Hrs.

**FAILURE CODE:**

15	Calibration
----	-------------