

Technical Service Bulletin

NUMBER: 23-02-00

GROUP: Body

DATE: Feb. 4, 2000

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of <bx>DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 23-20-99 REV. A DATED AUGUST 13, 1999 WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDE ADDITIONAL MODELS AND PARTS INFORMATION.**

SUBJECT:

Internal Emergency Trunk Release

MODELS:

1995 – 2000 (JA) Breeze/Cirrus/Stratus
1996 – 2000 (JX) Sebring Convertible
****1993 – 2000 (LH) Concorde/Intrepid/LHS/New Yorker/Vision/300M****
1995 – 2000 (PL) Neon

NOTE: THIS BULLETIN IS PROVIDED TO IDENTIFY THE PARTS AND PROCEDURES NECESSARY TO INSTALL AN INTERNAL EMERGENCY TRUNK RELEASE. RELEASE INSTALLATION EXPENSE IS SHARED BY DAIMLERCHRYSLER AND THE CUSTOMER. DAIMLERCHRYSLER WILL REIMBURSE YOU FOR THE LABOR ONLY. THE CUSTOMER IS RESPONSIBLE FOR THE PART EXPENSE. REFER TO WARRANTY BULLETIN D-99-20 FOR CLAIMING THE LABOR EXPENSE.

DISCUSSION:

DaimlerChrysler Corporation is now offering internal emergency trunk releases for the selected vehicles listed above. Other applicable passenger vehicles will be announced as soon as the parts are available. The trunk releases are packaged in a kit containing all necessary parts and a detailed instruction sheet.

PARTS REQUIRED:

1	05016812AA	Kit, Emergency Trunk Release,	1995 – 2000	JA
**1	05016813AA	Kit, Emergency Trunk Release,	1993 – 1997	LH **
1	05016810AA	Kit, Emergency Trunk Release,	1998 – 2000	LH
1	05016809AA	Kit, Emergency Trunk Release,	2000	PL W/Remote Entry
1	05016811AA	Kit, Emergency Trunk Release,	1994 – 1999	PL
			2000	PL W/Manual Entry
1	05016814AA	Kit, Emergency Trunk Release,	1996 – 2000	JX

POLICY: Customer Satisfaction Announcement

TIME ALLOWANCE:
Labor Operation No. 23-41-25-95 1.2 Hrs.

FAILURE CODE: XX – Service Adjustment