

Technical Service Bulletin

NUMBER: 08-033-00

GROUP: Electrical

DATE: Nov. 3, 2000

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Cold CD - fault code

MODELS:

2001	(AN)	Dakota
2001	(DN)	Durango
2001	(JR)	Sebring Sedan/Stratus Sedan
2001	(LH)	Concorde/ Intrepid/LHS/300M
2001	(PL)	Neon
2001	(PT)	PT Cruiser
2001	(WJ)	Grand Cherokee
2001	(WG)	Grand Cherokee (International Markets)

DISCUSSION:

A fault code may be set in the radio when performing diagnostics using the DRB III®. The code reads "Cold CD". The fault code is not displayed to the customer and is only displayed when performing diagnostics. The fault code was intended to be displayed if the CD player was operated in extreme cold temperatures. This code should be disregarded whenever it is encountered. The fault code will be eliminated in future radios.

POLICY:

Information Only