

International Technical Service Bulletin

NUMBER: I26-802-02

GROUP: Revisions

DATE: Jan. 21, 2002

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of Chrysler International.

SUBJECT:

Owner Manual Addendum - Cargo Load Barrier Warning

MODELS:

2002 PL Neon

DISCUSSION:

An Owner's Manual Addendum for Cargo Load Barrier Warning is available for 2002 PL vehicles. This addendum can be found and printed from ITIL CD 033 or later. Locate the TSB by document number I26-802-02.

All unsold vehicles in dealer/distributor inventory should have the addendum placed in the Owner's Manual.

POLICY:

Information Only.

OWNER'S MANUAL ADDENDUM

THIS ADDENDUM ADDS THE FOLLOWING WARNING TO THE CARGO LOAD BARRIER SECTION OF YOUR OWNER'S MANUAL

CARGO LOAD BARRIER—IF EQUIPPED

WARNING!

The cargo load barrier deters cargo from the trunk compartment from entering the interior compartment during frontal impact. Cargo entering the interior compartment may cause injury to occupants and/or damage to the seat if the cargo load barrier hooks are not attached to the brackets.

DaimlerChrysler Corporation

81-426-02083A

81-426-02084A

81-426-02087A

81-426-02193A

81-426-02964A