

Technical Service Bulletin

Number: 23-13-99

Group: Body

Date: April 30, 1999

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

High Window Cranking Efforts Or Slow Power Window Operation

MODELS:

2000 (PL) Neon

NOTE: THIS BULLETIN APPLIES TO VEHICLES BUILT PRIOR TO MARCH 15, 1999 (MDH 0315XX).

DISCUSSION:

If a customer reports significantly more window cranking effort or significantly slower power window operation and it has been determined that the system is working as designed. The following procedure can be performed to help ease the cranking efforts by lubricating the glass run weatherstrip.

1. Roll the window all the way down.
2. Apply Mopar Weatherstrip Lubricant (p/n 04773427) to the entire length of the vertical sections of the glass run weatherstrip flocked lips.
3. Cycle the glass up and down at least 10 times.

POLICY: Information Only