

Technical Service Bulletin

NUMBER: 03-01-00

GROUP: Driveshafts

DATE: Feb. 4, 2000

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of <bx>DaimlerChrysler Corporation.

SUBJECT:

Driveshaft Removal Information

MODELS:

2000 (JA) Breeze/Cirrus/Stratus
2000 (JX) Sebring Convertible
2000 (PL) Neon
2001 (PT) PT Cruiser

DISCUSSION:

During any service that requires the removal of the driveshaft, it is extremely important that the driveshaft removal procedure in Group 3 of the appropriate service manual be followed. The Neon and PT Cruiser Service Manuals provide the instructions for the proper use of a puller (Tool 6790); this puller must be used. **Do not** hammer on the end of the CV joint to detach the steering knuckle from the shaft. This can cause internal damage to the shaft that may not be obvious until the completion of the repair.

POLICY: Information Only