



NUMBER: 08-010-03

GROUP: Electrical

DATE: Apr. 25, 2003

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Seat Belt Cinch Bar Service

MODELS:


2001 - 2003	(AB)	Ram Van/Wagon (Front Passenger Seat Belt Only)
1994	(BR)	Ram Pickup
1996- 2002	(BR/BE)	Ram Pickup
2001 - 2003	(DN)	Durango (Front Passenger Seat Belt Only)
1995 - 2000	(JA)	Breeze/Cirrus/Stratus
2001 - 2004	(JR)	Sebring Convertible/Sebring Sedan/Stratus Sedan
1996 - 2000	(JX)	Sebring Convertible
1995 - 2003	(PL)	Neon/SX 2.0
2001 - 2003	(PT)	PT Cruiser

DISCUSSION:

Any time the seat belt cinch bar (Fig. 1) is loose, missing or damaged it is no longer necessary to replace the seat belt assembly. Cinch bar repair kits are now available for the vehicles listed. If any component of the seat belt assembly has been damaged due to collision, the entire assembly must be replaced.

NOTE: THE CINCH BAR, CINCH BAR COVER OR ANY OTHER COMPONENT OF THE SEAT BELT ASSEMBLY MUST NEVER BE PAINTED.

NOTE: INSTALLATION INSTRUCTIONS ARE INCLUDED WITH EACH KIT.



81191cd0

Fig. 1 SEAT BELT CINCH BAR

1 - Seat Belt

2 - Cinch Bar Mechanism

PARTS REQUIRED:

NOTE: SELECT THE COLOR CLOSEST TO THE SEAT BELT ASSEMBLY COLOR.

Qty.	Part No.	Description
AR (1)	05114298AA	Kit, Seat Belt, Taupe
AR (1)	05114294AA	Kit, Seat Belt, Sandstone
AR (1)	05114295AA	Kit, Seat Belt, Slate Grey

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
23-13-16-01	Cinch Bar, Seat Belt - Front or Rear - One/Both - Replace	0.2 Hrs.
23-13-16-50	Cinch Bar - Replace - Each Additional	0.1 Hrs.

FAILURE CODE:

K4	Loose
81	Poor Fit