

Technical Service Bulletin

NUMBER: 23-34-99

GROUP: Body

DATE: Aug. 27, 1999

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Foam Blocks, Bumper Fascia Mounted

OVERVIEW:

This bulletin involves the removal of foam shipping blocks. The blocks are attached to the front and rear fascias with adhesive to protect the fascias during shipping.

MODELS:

2000 (PL) Neon

DISCUSSION:

All foam bumper blocks must be removed from the front and rear fascias immediately upon delivery to the dealer. Failure to remove the blocks immediately may result in adhesive residue remaining on fascia. Use MOPAR Supper Kleen part number 04886330AA to remove any adhesive remaining after foam blocks are removed.

POLICY: Information Only