



NUMBER: 19-010-04

GROUP: Steering

DATE: November 29, 2004

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Power Steering Fluid Contamination

MODELS:

2004 - 2005	(CS)	Pacifica
2004 - 2005	(DR/DH)	Ram Truck
2004 - 2005	(HB)	Durango
2004 - 2005	(JR)	Sebring Convertible/Sebring Sedan/Stratus Sedan
2004 - 2005	(KJ)	Liberty
2005	(LX)	300/Magnum
2004 - 2005	(PL)	Neon/SRT4
2004 - 2005	(PT)	PT Cruiser
2004 - 2005	(RG)	Chrysler Voyager
2004 - 2005	(RS)	Town & Country/Caravan/Voyager
2004 - 2005	(ST)	Sebring Coupe/Stratus Coupe
2004 - 2005	(TJ)	Wrangler
2004 - 2005	(ZB)	Viper

DISCUSSION:

Do not use fluids or supplements that contain Teflon as they will cause a restriction at the filter in the power steering fluid reservoir, causing severe damage to the steering system. The power steering fluid used in Chrysler Group vehicles is an engineered product, the addition of **ANY** unapproved fluids or supplements can interfere with the proper function of the fluid and cause damage to the steering system. To ensure the performance and durability of Chrysler Group steering systems, **use only Mopar Power Steering Fluid +4, ATF+4 Automatic Transmission Fluid, or equivalent (MS-9602), in the power steering system.**

POLICY:

Information Only.



Stick with the Specialists™